

1. 측정결과 - 2021. 12. 06.











측정 장비 (종류/수량)	시료번호	측정 지점	유량 (ℓ/분)	측정 일시 (분)	측정 결과 (f/cc)	검출석면의 종류
KMS-5100 / 8대	#1	부지경계선1	9.98	245	0.0012	검출한계 이하
	#2	부지경계선2	9.95	245	0.0014	검출한계 이하
	#3	부지경계선3	9.97	245	0.0012	검출한계 이하
	#4	부지경계선4	9.95	245	0.0012	검출한계 이하
	#5	위생설비입구	9.96	45	0.0040	이하
	#6	작업장주변	9.96	125	0.0035	이하
	#7	폐기물반출구1	9.95	45	0.0036	이하
	#8	폐기물반출구2	9.94	45	0.0033	이하
	#9	폐기물반출구3	9.96	45	0.0036	이하
	#10	폐기물반출구4	9.95	45	0.0036	이하











- 측정시간(시작, 종료)은 측정사진대지 참조.

- 석면안전관리법 시행령 석면배출허용기준 0.01개/cc 이하

2. 측정사진

투입장비 종류 / 수량 KMS-5100 / 8대

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(f/cc)
부지경계선1			0.0012
	측정 시작 시간 09:35 측정 종료 시간 13:40		
부지경계선2			0.0014
	측정 시작 시간 09:40 측정 종료 시간 13:45		
부지경계선3			0.0012
	측정 시작 시간 09:45 측정 종료 시간 13:50		
부지경계선4			0.0012
	측정 시작 시간 09:50 측정 종료 시간 13:55		
위생설비 입구			0.0040
	측정 시작 시간 10:10 측정 종료 시간 10:55		

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(f/cc)
작업장주변			0.0035
	측정 시작 시간 10:00	측정 종료 시간 12:05	
폐기물 반출구1			0.0036
	측정 시작 시간 10:25	측정 종료 시간 11:10	
폐기물 반출구2			0.0033
	측정 시작 시간 11:10	측정 종료 시간 11:55	
폐기물 반출구3			0.0036
	측정 시작 시간 13:30	측정 종료 시간 14:15	
폐기물 반출구4			0.0036
	측정 시작 시간 14:00	측정 종료 시간 14:45	











1. 측정결과 - 2021. 12. 07.











측정 장비 (종류/수량)	시료번호	측정 지점	유량 (ℓ/분)	측정 일시 (분)	측정 결과 (f/cc)	검출석면의 종류
KMS-5100 / 8대	#1	부지경계선1	9.97	245	0.0014	검출한계 이하
	#2	부지경계선2	9.98	245	0.0012	검출한계 이하
	#3	부지경계선3	9.96	245	0.0014	검출한계 이하
	#4	부지경계선4	9.98	245	0.0012	검출한계 이하
	#5	위생설비입구	9.97	45	0.0036	이하
	#6	작업장주변	9.96	125	0.0035	이하
	#7	폐기물반출구1	9.99	45	0.0040	이하
	#8	폐기물반출구2	9.98	45	0.0036	이하
	#9	폐기물반출구3	9.96	45	0.0040	이하
	#10	폐기물반출구4	9.97	45	0.0036	이하

- 측정시간(시작, 종료)은 측정사진대지 참조.
- 석면안전관리법 시행령 석면배출허용기준 0.01개/cc 이하

2. 측정사진

투입장비 종류 / 수량 KMS-5100 / 8대

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(f/cc)
부지경계선1			0.0014
	측정 시작 시간 09:35 측정 종료 시간 13:40		
부지경계선2			0.0012
	측정 시작 시간 09:40 측정 종료 시간 13:45		
부지경계선3			0.0014
	측정 시작 시간 09:45 측정 종료 시간 13:50		
부지경계선4			0.0012
	측정 시작 시간 09:50 측정 종료 시간 13:55		
위생설비 입구			0.0036
	측정 시작 시간 10:10 측정 종료 시간 10:55		

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(f/cc)
작업장주변			0.0035
	측정 시작 시간 09:55	측정 종료 시간 12:00	
폐기물 반출구1			0.0040
	측정 시작 시간 10:20	측정 종료 시간 11:05	
폐기물 반출구2			0.0036
	측정 시작 시간 13:10	측정 종료 시간 13:55	
폐기물 반출구3			0.0040
	측정 시작 시간 13:50	측정 종료 시간 14:35	
폐기물 반출구4			0.0036
	측정 시작 시간 14:10	측정 종료 시간 14:55	










1. 측정결과 - 2021. 12. 08.

측정 장비 (종류/수량)	시료번호	측정 지점	유량 (ℓ/분)	측정 일시 (분)	측정 결과 (f/cc)	검출석면의 종류
KMS-5100 / 6대	#1	부지경계선1	9.96	245	0.0012	검출한계 이하
	#2	부지경계선2	9.97	245	0.0014	검출한계 이하
	#3	부지경계선3	9.93	245	0.0012	검출한계 이하
	#4	부지경계선4	9.96	245	0.0012	검출한계 이하
	#5	위생설비입구	9.96	45	0.0036	이하
	#6	작업장주변	9.94	125	0.0032	이하
	#7	폐기물보관지점1	9.97	45	0.0033	이하
	#8	폐기물보관지점2	9.98	45	0.0033	이하

- 측정시간(시작, 종료)은 측정사진대지 참조.
- 석면안전관리법 시행령 석면배출허용기준 0.01개/cc 이하

2. 측정사진

투입장비 종류 / 수량 KMS-5100 / 6대

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(f/cc)
부지경계선1			0.0012
	측정 시작 시간 09:35	측정 종료 시간 13:40	
부지경계선2			0.0014
	측정 시작 시간 09:38	측정 종료 시간 13:43	
부지경계선3			0.0012
	측정 시작 시간 09:40	측정 종료 시간 13:45	
부지경계선4			0.0012
	측정 시작 시간 09:43	측정 종료 시간 13:48	
위생설비 입구			0.0036
	측정 시작 시간 09:58	측정 종료 시간 10:43	

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(f/cc)
작업장주변 측정 시작 시간 09:55	 측정 종료 시간 12:00		0.0032
폐기물 보관지점1	 측정 시작 시간 13:05	 측정 종료 시간 13:50	0.0033
폐기물 보관지점2	 측정 시작 시간 13:07	 측정 종료 시간 13:52	0.0033

1. 측정결과 - 2021. 12. 09.

측정 장비 (종류/수량)	시료번호	측정 지점	유량 (ℓ/분)	측정 일시 (분)	측정 결과 (f/cc)	검출석면의 종류
KMS-5100 / 6대	#1	부지경계선1	9.95	245	0.0012	검출한계 이하
	#2	부지경계선2	9.94	245	0.0012	검출한계 이하
	#3	부지경계선3	9.95	245	0.0014	검출한계 이하
	#4	부지경계선4	9.94	245	0.0012	검출한계 이하
	#5	위생설비입구	9.94	45	0.0037	이하
	#6	작업장주변	9.96	125	0.0035	이하
	#7	음압기공기배출구	9.95	45	0.0036	이하
	#8	폐기물반출구	9.95	45	0.0040	이하







- 측정시간(시작, 종료)은 측정사진대지 참조.

- 석면안전관리법 시행령 석면배출허용기준 0.01개/cc 이하

2. 측정사진

투입장비 종류 / 수량 KMS-5100 / 6대

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(f/cc)
부지경계선1			0.0012
	측정 시작 시간 09:30	측정 종료 시간 13:35	
부지경계선2			0.0012
	측정 시작 시간 09:32	측정 종료 시간 13:37	
부지경계선3			0.0014
	측정 시작 시간 09:36	측정 종료 시간 13:41	
부지경계선4			0.0012
	측정 시작 시간 09:39	측정 종료 시간 13:44	
위생설비 입구			0.0037
	측정 시작 시간 09:50	측정 종료 시간 10:35	

측정지점	비산측정 시작 사진	비산측정 종료 사진	결과(f/cc)
<p data-bbox="188 394 316 427">작업장주변</p>	 <p data-bbox="357 546 624 580">측정 시작 시간 09:44</p>	 <p data-bbox="788 546 1054 580">측정 종료 시간 11:49</p>	<p data-bbox="1267 394 1358 427">0.0035</p>
<p data-bbox="188 745 316 801">음압기공기 배출구</p>	 <p data-bbox="357 909 624 943">측정 시작 시간 14:35</p>	 <p data-bbox="788 909 1054 943">측정 종료 시간 15:20</p>	<p data-bbox="1267 757 1358 790">0.0036</p>
<p data-bbox="204 1108 288 1164">폐기물 반출구</p>	 <p data-bbox="357 1272 624 1305">측정 시작 시간 14:33</p>	 <p data-bbox="788 1272 1054 1305">측정 종료 시간 15:18</p>	<p data-bbox="1267 1120 1358 1153">0.0040</p>